



Hamilton Center
1401 Brentwood Parkway NE
Washington, DC

Comprehensive Facility Condition Assessment
And Space Utilization Study
DCAM-12-NC-0158

May 13, 2013

Submitted to:

Ms. Cassandra White
Capital Program Financial & Systems Manager
Department of General Services – Construction Division
2000 14th Street NW, 8th Floor
Washington, DC 20009

4tell™ Solutions, LP

15 Franklin St

Portland, ME 04101

207.828.7900

www.4tellsolutions.com



Innovation for the Built Environment

economic · energy · environmental · social

This report includes data that shall not be disclosed outside the District and shall not be duplicated, used or disclosed in whole or in part for any purpose except for use in DC Department of General Services' capital planning process.

© 2013 4tell™ Solutions, LP. All Rights Reserved.

4tell, iPlan (patent pending) Building Blocks, and Innovation for the Built Environment are trademarks of 4tell™ Solutions, LP.






Hamilton Center

Date Assessed: 4/15/2013

Assessed By: EMG: Mark Chamberlain, EMG: Wayne Reid







Capital E	expenditures for Hamilton Center	Ŷ														
Element	Actions	Last	EUL*	RUL**	Qty.	Units	Unit Cost	Plan Type	2013	2014	2015	2016	2017	2018	2019	Total***
No.		Assigned	or	(Yrs)			\$		0	1	2	3	4	5	6	
A. SUBST	RUCTURE						¥				_					
	TRUCTURE SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B. SHELL B10	SUPERSTRUCTURE			<u> </u>		<u> </u>	<u> </u>									
B1032	Repair Cracking CMU and Concrete Walls	Poor - Fair	70	1	1.00	LS	\$10,000.00	Deferred Maintenance		\$10,000						\$10,000
B20	EXTERIOR ENCLOSURE															
B2011	Recaulk expansion and control joints	Poor	10	1	500.00	LF	\$13.16	Deferred Maintenance		\$6,580						\$6,580
B2011	Repair and Repoint Brick Masonry Exterior Walls	Fair - Good	75	1	250.00	SF	\$25.96	Deferred Maintenance		\$6,490						\$6,490
B2021	Paint Exterior Metal Grates at Windows	Fair	10	3	5,395.00	SF	\$2.25	Capital Replacement				\$12,139				\$12,139
B2021	Replace Exterior Windows	Poor - Fair	30	1	187,700.00	SF	\$62.80	Capital Replacement		\$11,787,560						\$11,787,560
B30	ROOFING					1										
B3011	Replace Modified Bitumen - Single Ply	Poor - Fair	20	1	80,000.00	SF	\$5.90	Deferred Maintenance		\$472,000						\$472,000
	SUB-TOTALS								\$0	\$12,282,630	\$0	\$12,139	\$0	\$0	\$0	\$12,294,769
C. INTERI	IORS INTERIOR CONSTRUCTION			<u> </u>		<u> </u>	1									
C1021	Replace Single Hollow Metal Door	Fair	50	5	65.00	EACH	\$1,200.00	Capital Replacement						\$78,000		\$78,000
					Ī	ı	1									
C30 C3012	INTERIOR FINISHES Paint Interior Walls	Fair - Good	8	4	180,700.00	SF	\$1.78	Capital Replacement					\$321,646			\$321,646
C3012	Replace Folding Wood Partition Walls	Fair - Good	25	1	2,294.00	SF	\$61.85	Capital Replacement		\$141,884			\$321,040			\$321,646 \$141,884
C3024	Replace Vinyl Tile Flooring	Fair	18	3	7,637.00	SY	\$67.75	Capital Replacement		V 111,00 1		\$517,407				\$517,407
C3024	Replace Vinyl Tile Flooring	Poor - Fair	18	1	1,486.00	SY	\$67.75	Deferred Maintenance		\$100,677						\$100,677
C3025	Replace Carpet Flooring	Poor	10	1	78.00	SY	\$67.40	Deferred Maintenance		\$5,257						\$5,257
C3025	Replace Carpet Flooring	Fair - Good	10	5	312.00	SY	\$67.40	Capital Replacement						\$21,029		\$21,029
C3031	Paint Interior Ceilings	Fair - Good	10	5	46,925.00	SF	\$11.60	Capital Replacement						\$544,330		\$544,330
C3032	Replace Acoustic Ceiling System	Poor - Fair	20	1	33,200.00	SF	\$9.68	Deferred Maintenance		\$321,376						\$321,376
					•		•		* -		• -					
C. INTER	IORS SUB-TOTALS								\$0	\$569,194	\$0	\$517,407	\$321,646	\$643,359	\$0	\$2,051,605
D. SERVIO	PLUMBING															
D2011 D2012	Replace Floor Mounted Toilets Replace Wall Hung Urinals	Good Fair	35 35	3	53.00 26.00	EACH EACH	\$1,455.00 \$1,235.00	Capital Replacement Capital Replacement				\$77,115 \$32,110				\$77,115 \$32,110
D2012 D2017	Replace Shower Components - Head, Arm,	Fair	20	3	38.00	EACH	\$1,233.00	Capital Replacement				\$20,216				\$20,216
D2018	Bypass, Stops, Handles Replace Floor Mounted Drinking Fountain	Fair	20	1	1.00	EACH	\$2,000.00	Capital Replacement		\$2,000		. ,				\$2,000
D2018	Install Drinking Fountain Third Floor Corridor	Poor	20	1	1.00	EACH	\$2,545.00	Deferred Maintenance		\$2,545						\$2,545
D2021	Replace Domestic Water Piping System	Fair - Good	30	5	180,700.00	SF	\$3.15	Capital Replacement						\$569,205		\$569,205
D2031	Replace Sanitary Waste Piping	Fair	50	5	180,700.00		\$1.37	Capital Replacement						\$247,559		\$247,559
D20	LINAC			1		ı	1			1		1			l	
D30 D3021	HVAC Replace Central Heating Boiler 2	Poor - Fair	30	1	1.00	EACH	\$199,525.53	Capital Replacement		\$199,526						\$199,526
D3021	Replace Central Heating Boiler 3	Poor - Fair	30	1	1.00	EACH	\$199,525.53			\$199,526						\$199,526
D3021	Replace Central Heating Boiler 1	Poor - Fair	30	1	1.00	EACH	\$199,525.53			\$199,526						\$199,526
D3022	Replace Boiler Room Piping & Valves	Poor	40	1	1.00	LS	\$25,000.00	Deferred Maintenance		\$25,000						\$25,000
D3023	Replace Fin-Tube Convectors - Wall	Fair	20	3	372.00	LF	\$130.00	Capital Replacement				\$48,360				\$48,360

Capital E	xpenditures for Hamilton Center															
Element No.	Actions	Last Assigned	EUL* or	RUL** (Yrs)	Qty.	Units	Unit Cost	Plan Type	2013	2014	2015	2016	2017	2018	2019	Total***
3041	Replace Central Air Handling Units	Fair	25	1	11.00	EACH	\$15,000.00	Capital Replacement		\$165,000						\$165,000
3041	Replace Unit Ventilators	Poor - Fair	15	1	69.00	EACH	\$7,685.00	Capital Replacement		\$530,265						\$530,265
3042	Replace Centrifugal Roof Exhaust Fan Systems	Poor	15	1	2.00	EACH	\$2,585.00	Deferred Maintenance		\$5,170						\$5,170
3042	Replace Commercial Kitchen Exhaust System	Poor	20	1	1.00	EACH	\$11,327.01	Deferred Maintenance		\$11,327						\$11,327
3042	Replace Metal Exhaust Hoods	Poor	20	1	17.00	EACH	\$2,500.00	Deferred Maintenance		\$42,500						\$42,500
40	FIRE PROTECTION SYSTEMS			I												
4031	Replace Fire Extinguishers	Fair - Good	5	2	30.00	EACH	\$250.00	Capital Replacement			\$7,500					\$7,500
50	ELECTRICAL SYSTEMS						I									
5012	Replace Panelboards - 120/208volts, 200amp	Poor - Fair	30	1	12.00	EACH	\$3,525.00	Capital Replacement		\$42,300						\$42,300
5012	Replace Main Electrical Switchgear	Poor - Fair	30	1	2,000.00	AMP	\$31.95	Capital Replacement		\$63,900						\$63,900
5022	Upgrade to T8 Fixtures	Fair	20	5	180,700.00	SF	\$2.80	Capital Replacement						\$505,960		\$505,960
5037	Replace Central Fire Alarm Panel	Poor	15	1	1.00	EACH	\$12,000.00	Capital Replacement		\$12,000						\$12,000
5037	Replace existing horn with horn/strobe	Poor	15	1	35.00	EACH	\$308.04	Deferred Maintenance		\$10,781						\$10,781
	CES SUB-TOTALS								\$0	\$1,511,365	\$7,500	\$177,801	\$0	\$1,322,724	\$0	\$3,019,39
	MENT & FURNISHING EQUIPMENT				1 1		1									
10 1093	Remove Abandoned Walk-in Coolers	Poor	30	1	2.00	LS	\$2,500.00	Deferred Maintenance		\$5,000						\$5,000
1093	Replace Commercial Kitchen Food Service Equipment	Fair	30	5	1.00	LS	\$25,000.00	Capital Replacement						\$25,000		\$25,000
20	FURNISHINGS			<u> </u>			T							1		
20 20	Replace E20 Furnishings	Fair - Good	30	3	180,700.00	SF	\$0.13	Capital Replacement				\$23,491				\$23,491
	· •			•	<u>'</u>											. ,
	MENT & FURNISHING SUB-TOTALS								\$0	\$5,000	\$0	\$23,491	\$0	\$25,000	\$0	\$53,491
	AL CONSTRUCTION AND DEMOLITION AL CONSTRUCTION AND DEMOLITION SUE	R TOTALS							\$ 0	\$0	\$0	\$0	\$ 0	\$0	\$0	\$0
	ING SITEWORK	3-101AL3							ΨΨ	+ + + + + + + + + + + + + + + + + + + +	Ψ	ΨΟ		40	Ψ0	Ψ-
20	SITE IMPROVEMENTS															
2021	Repair Damaged Concrete Pavement in Parking Lot and Drive Lane	Poor - Fair	30	1	8,180.00	SF	\$8.09	Deferred Maintenance		\$66,176						\$66,176
2021	Replace Concrete Paved Parking Lot	Fair	30	5	13,650.00	SF	\$8.09	Capital Replacement						\$110,429		\$110,429
2021	Replace Concrete Paved Drive Lane	Fair	30	5	32,720.00	SF	\$8.09	Capital Replacement						\$264,705		\$264,705
2025	Restripe Parking Lot	Poor - Fair	5	1	39.00	EACH	\$35.00	Deferred Maintenance		\$1,365					\$1,365	\$2,730
2031	Replace Cracking and Spalling Concrete Sidewalks	Poor	25	1	1,880.00	LF	\$33.13	Deferred Maintenance		\$62,284						\$62,284
2033	Install Metal Handrails at Site Steps	Poor	30	1	24.00	LF	\$47.39	Deferred Maintenance		\$1,137						\$1,137
32041	Replace Chain Link Galvanized Fence	Poor - Fair	15	1	530.00	LF	\$5.00	Deferred Maintenance		\$2,650						\$2,650
2053	Re-grading landscape and establishment of ground cover	Poor - Fair	50	1	555.00	SY	\$26.39	Deferred Maintenance		\$14,646						\$14,646

Capital E	pital Expenditures for Hamilton Center															
Element No.	Actions	Last Assigned	EUL* or	RUL** (Yrs)	Qty.	Units	Unit Cost	Plan Type	2013	2014	2015	2016	2017	2018	2019	Total***
G30	SITE CIVIL/MECHANICAL UTILITIES															
G30	Replace G30 Site Civil/Mechanical Utilities	Fair - Good	50	5	230,000.00	SF	\$0.56	Capital Replacement						\$128,800		\$128,800
G40	SITE ELECTRICAL UTILITIES															
G40	Replace G40 Site Electrical Utilities	Fair	50	5	230,000.00	SF	\$0.89	Capital Replacement						\$204,700		\$204,700
G4092	Replace Emergency Generator, 30 kW	Fair	25	3	1.00	EACH	\$20,670.00	Capital Replacement				\$20,670				\$20,670
G. BUILD	ING SITEWORK SUB-TOTALS								\$0	\$148,259	\$0	\$20,670	\$0	\$708,633	\$1,365	\$878,928
Z. GENER	RAL															
Z. GENER	RAL SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
						Exp	enditure Totals per Year	\$0	\$14,516,448	\$7,500	\$751,508	\$321,646	\$2,699,716	\$1,365	\$18,298,183	
								FCI† By Year	0.00%	24.12%	0.01%	1.25%	0.53%	4.49%	0.00%	
							CRV***	\$60,187,556								

Notes

- * EUL is the Estimated Useful Life of an Asset
- ** RUL is the Remaining Useful Life of an Asset
- *** Non-Escalated and Non-Inflated Adusted Dollars
- + FCI Formula (As Currently Programmed):

(Deferred Maintenance + Capital Renewal + Capital Replacement)/(Building Replacement Value)



Routine I	outine Maintenance Expenditures for Hamilton Center															
Element No.	Actions	Last Assigned	EUL* or	RUL** (Yrs)	Qty.	Units	Unit Cost	Plan Type	2013	2014	2015	2016	2017	2018	2019	Total***
A CLIDOT	RUCTURE						\$		0	1	2	3	4	5	6	
	RUCTURE RUCTURE SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$ 0
B. SHELL	ROCTORE SOB-TOTALS								ų,	Ψ0	40	Ψ	Ψ	ų,	-	Ψ
	SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C. INTER																
	ORS SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D. SERVIO									\$0	\$ 0	\$0	\$0	\$0	\$0	\$0	\$0
	CES SUB-TOTALS MENT & FURNISHING								\$ 0	ψU	ΦU	ψU	ψU	\$ 0	φU	ΦU
	MENT & FURNISHING SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	AL CONSTRUCTION AND DEMOLITION											Y	Y	,		¥-
	AL CONSTRUCTION AND DEMOLITION SUB	-TOTALS							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
	ING SITEWORK															
	ING SITEWORK SUB-TOTALS								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Z. GENER Z10	GENERAL REQUIREMENTS		<u> </u>	1	1 1		<u> </u>									
	Replace Z1010.1 Consider: Access Contro															
Z1010.1	Investmentsl	Good	10	0	1.00	LS	\$97,440.00	Plant Adaptation	\$97,440							\$97,440
Z1010.2	Replace Z1010.2 Consider: ADA Investments	Good	10	0	1.00	LS	\$88,000.00	Plant Adaptation	\$88,000							\$88,000
Z1010.3	Replace Z1010.3 Consider: Fire Protection Investments	Good	10	0	1.00	LS	\$1,366,387.00	Plant Adaptation	\$1,366,387							\$1,366,387
Z1010.4	Consider Installing Green Roof on all flat roof sections. Refer to report for details	Fair	50	0	80,000.00	SF	\$12.23	Plant Adaptation	\$978,240							\$978,240
Z1010.4	Consider Green Roof Structural Evaluation by Engineer. Refer to report for details	Fair	50	0	1.00	LS	\$7,500.00	Plant Adaptation	\$7,500							\$7,500
Z1010.5	Replace Z1010.5 Consider: Haz Mat Investments	Good	10	0	1.00	LS	\$500.00	Plant Adaptation	\$500							\$500
Z1010.6	Replace Z1010.6 Consider: LEED Investments	Good	10	0	1.00	LS	\$253,523.00	Plant Adaptation	\$253,523	_						\$253,523
Z1010.7	Replace Z1010.7 Consider: Safety Security Investments	Good	10	0	1.00	LS	\$394,559.00	Plant Adaptation	\$394,559							\$394,559
7 GENER	AL SUB-TOTALS		_				_		\$3,186,149	\$0	\$0	\$0	\$0	\$0	\$0	\$3,186,149
L. OLIVLIN	AL GOD TO TALO					Expenditure Totals per Year			T -	\$0	\$0	\$0	\$0	\$0	\$3,186,149	
	CRV*** \$60,187,556		75,156,110			7.				ψο, 100, 140						
							OILV	ψου, τον ,550								

Notes


^{* -} EUL is the Estimated Useful Life of an Asset

^{** -} RUL is the Remaining Useful Life of an Asset

^{*** -} Non-Escalated and Non-Inflated Adusted Dollars



Capital Expenditure Costing By Level 1 Uniformat by Year for Hamilton Center





			π
Ac	cess Control Questionnaire for Hamilton	Cente	r
Ac	cess Control	Yes/ No	Comments
1	Does the facility have a key card proximity entry system?	No	None
2	Are all windows at grade level locked or fixed at all times (to prevent passing of contraband into the facility)?	Yes	
3	There is one clearly marked and designated entrance for visitors?	Yes	
4	Signs are posted for visitors to report to main office or through a designated entrance?	Yes	Small paper sign
6	Access to bus loading area is restricted to other vehicles during loading/unloading?	No	Street level pick up / drop off
7	Lighting is provided at entrances and points of possible intrusion?	No	Missing / damaged lights
8	Outside hardware has been removed from all doors except at points of entry?	No	
9	Basement windows are protected with grill or well cover?	No	No basement windows, ground level
10	"Restricted" areas are properly identified?	Yes	Locked doors
	Access to electrical panels is restricted?	No	Unlocked panels
12	Are there control gates to separate gym, cafeteria, stage, lobby and restrooms from rest of school and classrooms during after hours without changing means of egress?	No	Would require a minimum of (4) gates
13	Are all perimeter doors equipped with recessed magnetic contact – door position door sensors?	Yes	Recessed contacts
14	Are interior doors with specific vulnerability equipped with door position monitoring sensors?	No	None observed



ADA Questionnaire for Hamilton Center				
Parking				
Accessibility Item	Qty.	Unit Cost	Unit	Est. Cost
Adequate number of designated parking stalls and signage for cars are not provided?	2	\$165.00	EACH	\$330
Adequate number of designated parking stalls and signage for vans are not provided?	1	\$220.00	EACH	\$220
Signage indicating accessible parking spaces for cars and vans are not provided?	2	\$120.00	EACH	\$240
1 IN EVERY 8 ACCESSIBLE SPACES SHOULD BE DESIGNATED FOR A VAN WITH A MINIMUM OF ONE PROVIDED.				
Access aisles adjacent to parking spaces, crossing hazardous vehicle areas, from main roadways or public transportation stops to the building sidewalks and entrances are not provided?	1	\$6.50	LF	\$7
Curb ramps are required from the parking area to the sidewalks providing access to the building?	1	\$950.00	EACH	\$950
Passenger drop off areas are not provided at the building entrances or access routes?	1		EACH	
Drop off area is for shuttle service, etc. Individual cars and vans use the HC space. Limit use to enclosed malls and properties with known needs.				
Signage directing to accessible parking or accessible building entrances to the facility are not provided?	2	\$120.00	EACH	\$240
Use when main entrance is not accessible and directions are required to alternate entrance.				
Comments: Stalls not clearly marked, no signs				
	Parki	ing Estimate	d Cost:	\$1,987

Qty.	Unit Cost	Unit	Est. Cost
1	\$325.00	LF	\$325
0	\$40.00	LF	\$0
	1	1 \$325.00	1 \$325.00 LF

Entrances/Exits				
Accessibility Item	Qty.	Unit Cost	Unit	Est. Cost
Install buzzer or intercom for assistance and service at exterior entrance doors or parking space?	0	\$500.00	EACH	\$0
Existing entrance doors are not wide enough to accommodate wheelchair access and clear floor space beside the door swing is lacking?	6	\$1,250.00	EACH	\$7,500



ADA Questionnaire for Hamilton Center						
Vestibule doors are set too close to the front doors for wheelchair access?	0	\$2,250.00	EACH	\$0		
Lever action hardware is not provided at all accessible locations?	6	\$65.00	EACH	\$390		
Comments: Lever action hardware required , no ramp to facility						
Entrances/Exits Estimated Cost: \$7,89						

Paths of Travel Accessibility Item	Qty.	Unit Cost	Unit	Est. Cost
Obstacle or protrusion from wall impeding access? Describe condition, location, and repair scope to correct	. 0			
Existing carpeting is not securely attached or has a pile thickness exceeding 1/2"?	0		SY	
Stair handrails do not extend beyond the top and bottom risers?	16	\$350.00	EACH	\$5,600
Compliant signage indicating accessible entrances and general information is not provided?	2	\$60.00	EACH	\$120
Stair handrails do not extend beyond the top and bottom risers?	16	\$125.00	EACH	\$2,000
Modify location of telephones installed higher than what is essential for basic operation?	0	\$400.00	EACH	\$0
Lower objects mounted higher than 27" off the floor, project more than 4" into walks, halls, corridors, passageways, or aisles?	0		EACH	
Watercoolers and telephones may be an issue if they are wall mounted above 27". ADAAG intent is to enable the cane of a blind person to detect the object before bumping into it.				
Add visual alarm to existing audible fire alarm? Only if audible alarm is present, required by building codes in affect when constructed.	32	\$250.00	EACH	\$8,000
Install cup dispenser at an existing non-conforming water fountain?	10	\$25.00	EACH	\$250
Comments:	he of Tro	vel Estimate	d Cast	¢45.070
Pat	is or ira	vei Estimate	u Cost:	\$15,970

Elevators				
Accessibility Item	Qty.	Unit Cost	Unit	Est. Cost
Elevator control panel and hall buttons are mounted higher than 54" above the floor?	1	\$6,000.00	EACH	\$6,000
Raised elevator markings at control panel and hall buttons are not provided in Braille and Standard Alphabet?	1	\$350.00	EACH	\$350
Audible signals are not provided at floor level changes or elevator lobbies indicating car arrival?	1	\$400.00	EACH	\$400
Add visual alarm to existing audible fire alarm?	1	\$250.00	EACH	\$250
Safety stops not installed in elevator doors?	1	\$6,000.00	EACH	\$6,000
Elevator communication equipment not set up for speech impaired communication?	1	\$2,600.00		\$2,600
Comments:				
Facility non elevated				
	Elevat	ors Estimate	d Cost:	\$15,600



Total Estimated Cost:

\$64,672

ADA Questionnaire for Hamilton Center

Restrooms				
Accessibility Item	Qty.	Unit Cost	Unit	Est. Cost
Existing restroom doors are not wide enough to accommodate wheelchair access, and clear floor space beside the door swing is lacking?	10	\$1,250.00	EACH	\$12,500
Lever action hardware is not provided at all accessible locations?	10	\$65.00	EACH	\$650
Install grab bars in accessible stalls at 36" above the floor?	10	\$325.00	EACH	\$3,250
Modify existing toilet room accessories and mirrors?	10	\$200.00	EACH	\$2,000
Modify existing lavatory faucets to paddle type faucets?	10	\$300.00	EACH	\$3,000
Wrap drain pipes below lavatory with insulation; protect against contact with hot, sharp, or abrasive surfaces?	10	\$50.00	EACH	\$500
Add pull station alarm in unisex bathroom?	2	\$500.00	EACH	\$1,000
Comments:				
Restrooms are NOT ADA compliant				
	Restroo	ms Estimate	d Cost:	\$22,900



Fir	Fire Protection Questionnaire for Hamilton Center					
Sp	rinkler and Suppression	Yes/ No	Comments			
1	Does the facility have a fire sprinkler system?	No	Non sprinkled building			
2	Does the facility have wall mounted fire extinguishers?	Yes	Sept. 2012			
3	Does the kitchen and cooking area have hood vent mounted fire suppression systems?	Yes				
4	Does combustion equipment have dedicated fire sprinkler system e.g. boilers, hot water heater?	No				

Inspection		Yes/ No	Comments
1	Are current fire protection system inspections up to date and onsite?	Yes	Main office
2	A record of Fire Inspection by the local or state Fire Officer is maintained?	Yes	Main office
3	Exit signs are clearly visible and pointing in the correct direction?	No	3rd floor damaged signs / missing signs, 2nd floor signs not lighted

Ala	arm and Annunciators	Yes/ No	Comments
1	Does the facility have monitored fire alarm system?	No	Staff calls fire department
2	Is the fire alarm control panel solid-state, modular design type, incorporating the following standard features: lamp test, red alarm and amber LEDs per zone, positive and negative ground fault indicators, power ON indicator, two (2) auxiliary form C alarm contacts with disconnect switches and lights, one (1) auxiliary form C trouble contact, regulated 24Vdc four-wire smoke detector power supply, and remote reset connection?	No	Antiquated system
3	Is the power supply to the fire alarm control panel from an individual circuit?	No	
4	Does the activation of any initiating device including but not limited to manual pull stations, smoke detectors, heat detectors and flow switches shall cause all signals to sound continuously until manually reset; flash all visual alarm indicator lights; illuminate respective zone indicator lamps in the control panel; illuminate respective zone indicator lamps in the graphic display on the door of the control panel; and illuminate respective zone indicator lamps in the remote annunciator?	No	Pull stations only
5	Are the audible and visual devices such as combination horn/strobe indicating type wired to separate zones so that audible devices correctly provide code three temporal output and visual devices correctly provide ADA compliant strobe effect?	No	Bell only, no smoke detectors or strobes



Fir	Fire Protection Questionnaire for Hamilton Center					
6	Is the fire alarm wiring enclosed in 3/4" metal conduit raceway to the manufacturer's instructions?	Yes				
7	Is there a smoke detector directly above the fire alarm control panel?	No	None observed			
8	Are there smoke detectors within 5'-0" on each side of the fire doors? Are detectors tied into magnetic door holders to release fire doors upon alarm?	No	None observed			
9	Are there duct-type smoke detectors on the supply side of HVAC units rated greater than 2000 cfm but less than 15,000 cfm?	No	Not known			
10	Are there duct-type smoke detectors on both the supply side and return side of the HVAC units rated 15,000 cfm or more?	No	Not known			
11	Are there duct-type smoke detectors at all smoke damper locations within the HVAC system ductwork? Is there additional wiring to close the damper and turn off the associated HVAC unit?	No	Not known			



Green Roof Questionnaire for Hamilton Center Green Roof-2 Feasibility Questions Unit Cost Total Cost Label Qty. Green Roof 80000 SF \$12.23 \$978,240.00 All flat roofs Location Is the roof a sloped system? No Is the roof less than 5 years in age? No Does the roof have signficant amounts of penetration and Yes equipement? Will structural modification need to be made to support a Yes green roof? Comments As the building was not originally designed

Green Roof-1 Feasibility Questions		
Label	Qty.	Unit Cost Total Cost
Green Roof Structural Evaluation by Engineer	1 LS	\$7,500.00 \$7,500.00
Location	All flat roofs	
Is the roof a sloped system?	No	
Is the roof less than 5 years in age?	No	
Does the roof have signficant amounts of penetration and equipement?	Yes	
Will structural modification need to be made to support a green roof?	Yes	
Comments	As the building	y was not originally designed



На	Haz Mat Questionnaire for Hamilton Center				
As	bestos Containing Building Materials	Yes/ No	Comments		
1	Does the facility have a current AHERA Asbestos Inspection on File?	Yes	Main office		
2	Does the facility currently have a Asbestos Containing material O&M plan in place?	Yes	Main office		
3	Has all the material identified in the AHERA report been abated?	No	Not known		

Lead in Paint / Water		Yes/ No	Comments
1	Has the facility been tested for Lead Paint?	Yes	
2	Does the facility have a Lead containing paint O&M plan in place?	Yes	
3	Has all the lead identified in the LBP report been abated?	No	Not known
4	Has the facility been tested for Lead in Water?	Yes	
5	Does the facility have a Lead in water O&M plan in place?	Yes	

Fuel Storage Tanks		Yes/ No	Comments
1	Does the facility have a UST?	No	None observed
2	Does the tank have a leak detection system?	No	None observed
3	Does the facility have a AST?	No	None observed
4	Does the AST have a leak containment system?	No	None observed

PC	Bs	Yes/ No	Comments
1	Are transformers PCBs free?	No	Not known
2	Is there any known PCB containing equipment onsite?	No	Not known



LEED Scoresheet for Hamilton Center					
Sustaina	able Sites Poss	ible Points: Existing	26		
Credit 1	Is the school LEED Certified Design and Construction?	No	0		
	Level of Effort to Achieve: Hard				
Credit 2	Does the facility have a Building Exterior and Hardscape Management Plan? Level of Effort to Achieve: Easy	No	0		
Credit 3	Does the facility have an Integrated Pest Management, Erosion Control, and Landscape Management Plan? Level of Effort to Achieve: Easy	No	0		
Credit 4	Does the facility provide car pooling or Alternative Commuting Transportation options or incentives?	Yes	7		
Credit 5	Does the way the site is developed Protect or Restore Open Habitat?	N/A	0		
Credit 6	Does the facility have retention ponds rain gardens to control the quantity of Storm water? Level of Effort to Achieve: Hard	No	0		
Credit 7.1	Does the facility have non asphalt / macadam based paving such as light colored pavers or concrete? Level of Effort to Achieve: Hard	No	0		
Credit 7.2	Does the facility have a cool roof (white or light color roof surface) ? Level of Effort to Achieve: Hard	No	0		
Credit 8	Are measures installed preventing operable exterior lighting from encroaching on adjacent properties?	g Yes	1		
		Total:	8		

Water E	fficiency Pos	ssible Points: Existing	14
Prereq 1	The facility has a Minimum Indoor Plumbing Fixture and Fitting Level of Effort to Achieve: Hard	No	
Credit 1	Does the facility have a water meter for the whole building?	Yes	1
Credit 1	Does the facility have sub meters for boiler water, cooling tower water, irrigation water, fire sprinkler? Level of Effort to Achieve: Hard	No	0
Credit 2	Are all of the plumbing fixtures at the facility non-water saving devices?	Yes	0
	Are some of the plumbing fixture at the facility are non-water saving device (10-25%)?	N/A	0
	Are all of the plumbing fixture at the facility water saving devices (100%)? Level of Effort to Achieve:	No	0
Credit 3	Does the school use native planting that does not require irrigation?	Yes	2
	Does the school have an irrigation system with a rain gauge and time system. Level of Effort to Achieve: Hard	em? No	0
	Does the school hand water on an as needed basis?	Yes	1
Credit 4	Does the Cooling Tower utilize a Chemical Management System?	N/A	0



Does the Cooling Tower utilize a Non-Potable Water Source (not public drinking water system)? N/A 0 Total: 4

Energy a	Energy and Atmosphere Possible		35
Prereq 1	Does the school have an Energy Efficiency Best Management Practices policy? Level of Effort to Achieve: Easy	No	
Prereq 2	Has an energy audit been performed and were ECMs implemented to achieve Minimum Energy Efficiency Performance? Level of Effort to Achieve: Easy	No	
Prereq 3	Does the school have a Fundamental Refrigerant Management program?	N/A	
Credit 1	Is it feasible for the facility to achieve an EnergyStar rating of 71 or higher? Level of Effort to Achieve: Hard	No	0
Credit 2.1	Have building lighting and HVAC systems been Investigated and Analyzed for retro Commissioning?	No	0
Credit 2.2	Level of Effort to Achieve: Hard Has the school performed retro Commissioning of the building lighting and HVAC systems?	No	0
Credit 2.3	Level of Effort to Achieve: Hard Is the school performing ongoing Commissioning of the building lighting and HVAC systems? Level of Effort to Achieve: Hard	No	0
Credit 3.1	Does the school have a HVAC or Lighting —Building Automation System? Level of Effort to Achieve: Hard	No	0
Credit 3.2	Are the HVAC and lighting systems individually metered at 40%?	N/A	0
	Are the HVAC and lighting systems individually metered at 80% ?	N/A	0
Credit 4	Does the school use on-site or off-site renewable energy? Level of Effort to Achieve: Hard	No	0
Credit 5	Does the school have an Enhanced Refrigerant Management? Level of Effort to Achieve: Hard	No	0
Credit 6	Does the school have an Emissions Reduction Reporting program?	No	0
	Level of Effort to Achieve: Hard	Total:	0

Material	s and Resources	Possible Points:	10
		Existing	
Prereq 1	Does the school have a Sustainable Purchasing Policy?	Yes	
Prereq 2	Does the school have a Solid Waste Management Policy?	Yes	
Credit 1	Does the school have a Sustainable Purchasing program for Ongoing	No	0
	Consumables?		
	Level of Effort to Achieve: Easy		
Credit 2.1	Is a Sustainable Purchasing policy used for purchasing at least 40% of	No	0
	Electric-Powered Equipment?		
	Level of Effort to Achieve: Hard		



		_	
LEED So	oresheet for Hamilton Center		
Credit 2.2	Is a Sustainable Purchasing policy used for purchasing at least 40% of Furniture?	No	0
	Level of Effort to Achieve: Hard		
Credit 3	Is a Sustainable Purchasing policy used when making Facility Alterations and Additions?	No	0
	Level of Effort to Achieve: Hard		
Credit 4	Is a Sustainable Purchasing policy used to reduce Mercury content in Lamps purchased?	Yes	1
Credit 5	Is a Sustainable Purchasing policy used when making Food purchases at the school?	No	0
	Level of Effort to Achieve: Easy		
Credit 6	Has the school performed a Waste Stream Audit?	No	0
	Level of Effort to Achieve: Easy		
Credit 7	Has the school implemented a policy to reduce the quantity Ongoing Consumables going into landfills?	Yes	1
Credit 8	Has the school implemented a policy to reduce the quantity durable goods (furniture, equipment) going into landfills?	Yes	1
Credit 9	Does the school recycle building materials during construction which prevents material going to landfill?	No	0
	Level of Effort to Achieve: Hard		
		Total:	3

Indoor E	ndoor Environmental Quality Possible Points: Existing			15
Prereq 1	Has the school performed a Minimum Indoor Air Quality (IAQ) Performance evaluation of the facility? Level of Effort to Achieve: Hard		No	
Prereq 2	Is the facility and surrounding area smoke free - Environmental To Smoke (ETS) Control?	bacco	Yes	
Prereq 3	Does the school have a Green Cleaning Policy?		Yes	
Credit 1.1	Does the school have an Indoor Air Quality Management Program?		No	0
	Level of Effort to Achieve: Easy			
Credit 1.2	Does the school have Outdoor Air Delivery Monitoring?		No	0
	Level of Effort to Achieve: Hard			
Credit 1.3	Has the school modified the HVAC systems to allow Increased Ventilation	on?	No	0
	Level of Effort to Achieve: Hard			
Credit 1.4	Does the school have a plan to Reduce Particulates in Air Distribution?		No	0
	Level of Effort to Achieve: Hard Does the school have a policy to enhance IAQ performance during Faci	lity		
Credit 1.5	Alterations and Additions?	iity	No	0
	Level of Effort to Achieve: Hard			
Credit 2.1	Has the school performed an Occupant Survey for IAQ?		No	0
	Level of Effort to Achieve: Easy			
Credit 2.2	Does the school allow for the Controllability of Systems—Lighting by occupants?		No	0
	Level of Effort to Achieve: Hard			



LEED So	coresheet for Hamilton Center		
Credit 2.3	Does the school allow for the Occupant Comfort—Thermal Comfort Monitoring?	No	0
	Level of Effort to Achieve: Hard		
Credit 2.4	Does the school take advantage of Daylight and Views for tenant comfort?	No	0
	Level of Effort to Achieve: Not Feasible		
Credit 3.1	Does the school have a High Performance Cleaning Program?	Yes	1
Credit 3.2	Does the school have a Custodial Effectiveness Assessment?	Yes	1
Credit 3.3	Does the school Purchase Sustainable Cleaning Products and Materials?	Yes	1
Credit 3.4	Does the school use Sustainable Cleaning Equipment?	No	0
	Level of Effort to Achieve: Easy		
Credit 3.5	Does the school have Indoor Chemical and Pollutant Source Control?	No	0
	Level of Effort to Achieve: Easy		
Credit 3.6	Does the school have an Indoor Integrated Pest Management?	Yes	1
		Total:	4

Innovation	on in Operations	Possible Points: Existing	6
Credit 1.1	Does the school have an Innovation in Operations program?	No	0
	Level of Effort to Achieve: Easy		
Credit 2	Does the school have a LEED Accredited Professional on staff?	No	0
	Level of Effort to Achieve: Hard		
Credit 3	Is the school Documenting Sustainable Building Cost Impacts?	No	0
1	Level of Effort to Achieve: Hard		
		Total	0

Certified 40 to 49 points ● Silver 50 to 59 points ● Gold 60 to 79 points ● Platinum 80 to 110 points

Total: 19

21 Points to LEED Certification



Sa	afety-Security Questionnaire for Hamilton Center					
Со	mmunication	Yes/ No	Comments			
1	Do all areas of the school, including bathrooms, hallways, and offices, have the ability to receive an announcement via the P.A. System?	No				
2	Do all areas of the school have the ability to privately call the main office or for emergency?	No	No telephone, intercom system not functioning			
3	Does the general office, principal's office, assistant principal's office have CCTV receptacles?	Yes				
4	Is there an automated notification system to lockdown the building envelope at all exits including service doors and loading docks or all classrooms as necessary?	No	Security two way radios, over head PA system			

Mc	onitoring	Yes/ No	Comments
1	Does the facility have a monitored burglar alarm system?	Yes	DCPS
2	Are all classrooms and all other rooms that are grade-accessible will be equipped with motion detectors?	Yes	
3	Are all general corridor or lobby areas plus rooms with specific vulnerability (e.g., main office, principal's office, library, computer rooms, etc.) equipped with motion detectors?	Yes	
4	Is the main office and one or more additional locations(s) accessed by designated staff equipped with IDS arm/disarm keypads?	No	None observed
5	Are alarm monitoring and response performed by DCPS via their existing central alarm monitoring facility via either dial-up telephone lines or LAN/WAN?	Yes	

Su	Surveillance		Comments
1	Is there a video surveillance system that provides general surveillance of the site, common areas and building entry and exit points?	Yes	28 cameras
2	Does the facility have monitored video surveillance system at the interior?	Yes	Principal office
3	Does the facility have monitored video surveillance system at the exterior?	Yes	DCPS

Ex	Exterior Entry/Egress		Comments
1	Does the facility have exterior door hardware that allows controlled access to the building?	Yes	Very poor condition
2	Does the facility have exterior card access readers that allow controlled access to the building?	No	None
3	Does the facility have allow occupants a quick, unimpeded egress from the building?	Yes	Push bar poor condition, sticks



Safety-Security Questionnaire for Hamilton Center

Int	erior Entry/Egress	Yes/ No	Comments
1	Does the facility have interor door hardware that allows controlled access to classrooms?	Yes	Twist knob, key lock
2	Does the facility have interior card access readers that allow controlled access within the building?	No	None

lr	terior Entry/Egress	Yes/ No	Comments
1	Does the facility have Magnetometers that monitor for the entry of "unwanted items" into the building?	Yes	(1) magnetometer and (1) xray
2	Does the facility have equipment that allows announcements to be made during large gatherings?	Yes	large auditorium



Space Utilization for Hamilton Center

Entire School Comments [From Pathways 2012 Data]
Proposed Capacity (2012):

2003 Capacity: Proposed Capacity (2012):
Bldg SF: SF per Student:
Rationale:

Room [From iPlan]	Design ID [From iPlan]	Room Type [From iPlan]	Program Occupancy [From Pathways]	Design Occupancy [From Pathways]	Space (SQF) (Design [From Pathways]	Space (SQF) (Actual) [From iPlan]	Comments [From iPlan]
1		Building Services				2,500	Boiler Room
10		Building Services				0	Mech
100		Building Services				160	Mech
101		Building Services				350	Bookroom
102		Building Services				350	Storage
103		Building Services				160	Toilet
103		Building Services				480	Storage
105		Building Services				1,632	
109							Stage Toilet
		Building Services				160	
11		Building Services				0	Mech
111		Building Services				8,832	Auditorium
112		Building Services				3,360	Atrium
115		Building Services				140	Mech
116		Building Services				140	Mech
117		Building Services				140	Storage
118		Building Services				140	Storage
119		Building Services				135	Storage
12		Administration				1,034	Office
120		Building Services				135	Storage
121		Administration				312	Office Suite
122		Administration				627	Office Suite
123		Administration				117	Office Suite
124		Administration				42	Office Suite
125		Administration				288	Office Suite
126		Administration				270	Office Suite
127		Administration				165	Office Suite
128		Administration				165	Office Suite
129		Administration				165	Office Suite
13		Administration				352	Office
130		Administration				216	Office Suite
131		Administration				156	Office Suite
132		Administration				156	Office Suite
133		Administration				156	Office Suite
135		Auxiliary				120	Nurse Suite
136		Auxiliary				120	Nurse Suite
137		Auxiliary				120	Nurse Suite
138		Auxiliary				352	Nurse Suite
139		Auxiliary				154	Nurse Suite
14		Instruction				836	Classroom
140		Building Services	1			1,395	Locker Room
141		Building Services				308	Locker Room Area
142		Building Services				418	Locker Room Area
143		Auxiliary				7,480	Gymnasium
144		Auxiliary				420	Storage
145		Building Services				196	Storage
146		Building Services				390	Storage
147		Building Services				208	Storage
148		Building Services				286	Storage
149		Building Services				88	Storage
15		Administration				352	Office
150		Building Services				224	Storage
151		Building Services				1,395	Locker Room
151		Building Services				682	Locker Room Area
153		Building Services				418	Locker Room Area
155	-	Building Services				128	Storage
156		Instruction				770	Classroom
157		Instruction				770	Classroom



	for Hamilton Center		
158	Building Services	5,000	Corridor
159	Building Services	5,000	Corridor
16	Instruction	1,216	Classroom
160	Building Services	912	Corridor
161	Building Services Building Services	912	Corridor
162	Instruction	1,034	Classroom
163	Instruction	1,408	Classroom
165	Instruction	704	Classroom
166	Instruction	704	Classroom
167	Instruction	1,056	Classroom
168	Building Services	252	Storage
169	Instruction	704	
			Classroom
17	Administration	836	Office
170	Instruction	704	Classroom
171	Instruction	704	Classroom
172	Instruction	704	Classroom
173	Building Services	345	Storage
174	Instruction	1,200	Classroom
175	Instruction	1,034	Classroom
176	Instruction	616	Classroom
177	Instruction	704	Classroom
178	Instruction	704	Classroom
179	Instruction	704	Classroom
18	Administration	352	Office
180	Instruction	704	Classroom
181	Instruction	704	Classroom
182	Instruction	704	Classroom
183	Instruction	704	Classroom
184	Instruction	704	Classroom
185	Instruction	1,034	Classroom
186	Instruction	770	Classroom
187	Instruction	770	
			Classroom
188	Building Services	220	Storage
189	Building Services	336	Storage
19	Building Services	133	Storage
190	Building Services	238	Storage
2	Building Services	0	Mech
20	Building Services	224	Storage
200	Building Services	238	Storage
201	Building Services	238	Storage
204	Building Services	416	Mech
205	Building Services	272	Storage
206	Building Services	272	Storage
207	Building Services	272	Storage
208	Building Services	416	Storage
209			Media Center
	Auxiliary	3,480	
21	Building Services	210	Storage
210	Administration	299	Office
211	Administration	207	Office
212	Administration	220	Office
213	Administration	220	Office
215	Instruction	704	Classroom
216		704	
	Instruction		Classroom
217	Building Services	4,500	Corridor
218	Building Services	4,500	Corridor
219	Building Services	984	Corridor
220	Building Services	880	Corridor
221	Building Services	880	Corridor
23	Building Services Building Services	289	Storage
24	Building Services	56	Storage
25	Building Services	414	Storage
26	Building Services	252	Storage
	Building Services	208	Storage
		200	Jugo
27		224	
	Building Services Building Services	234 540	Storage Storage



ace Utilization for H	lamilton Center		
30	Building Services	306	Storage
32	Building Services	120	Storage
33	Building Services	465	Storage
34	Building Services	1,034	Kitchen
35	Building Services	3,040	Cafeteria
36	Administration	3,744	Administration Suite
37	Building Services	102	Storage
38	Building Services	102	Storage
39	Building Services	684	Storage
4	Building Services	0	Mech
40	Building Services	72	Storage
41	Building Services	270	Storage
42	Building Services	540	Storage
43	Building Services	270	Storage
44	Building Services	432	Storage
45	Building Services	495	Storage
46	Building Services	289	Storage
47	Administration	1,034	Conference Room
48	Building Services	308	Vestibule
49	Building Services	308	Vestibule
5	Building Services	0	Mech
50	Instruction	704	Classroom
51	Administration	704	Office
52	Instruction	704	
			Classroom
53	Instruction	704	Classroom
54	Instruction	1,034	Classroom
55	Building Services	1,962	Corridor
56	Building Services	1,962	Corridor
57	Building Services	920	Corridor
58	Instruction	1,200	Classroom
59		1,200	
	Instruction		Classroom
6	Building Services	0	Mech
60	Instruction	800	Classroom
61	Instruction	800	Classroom
62	Instruction	800	Classroom
63	Administration	325	Conference Room
64	Instruction	800	Classroom
65	Instruction	925	Classroom
66	Instruction	800	Classroom
67	Instruction	800	Classroom
68	Instruction	950	Classroom
7	Building Services	0	Mech
74	Instruction	1,350	Classroom
75	Instruction	1,034	Classroom
76	Administration	384	Office
77	Administration	252	Office
78	Administration	252	Office
79	Administration	336	Office
8	Building Services	0	Mech
80	Instruction Support	1,034	Computer Lab
81	Instruction	704	Classroom
82	Building Services	378	Vestibule
83	Building Services	840	Vestibule
86	Instruction	704	Classroom
87	Auxiliary	1,034	Library
88	Administration	294	Office
89	Building Services	81	Storage
9	Building Services	0	Mech
90	Building Services	81	Storage
91	Administration	528	Office
92	Administration	528	Office
93		950	Conference Room
	Administration		
94	Building Services	225	Storage
95	Building Services	49	Storage
96	Building Services	49	Storage
97	Instruction	950	Classroom



Space Utilization	Space Utilization for Hamilton Center										
99	Administration		1,265	Office							
	Floor Totals:		142,335								
	Property Totals:		142,335								

No 2012 Pathways Data has been Provided



Uniformat Level 2 Asset Condition Rating For Hamilton Center

		2012 iPlan Sc	oring		
Condition	Score		From	То	Rating
Good	10	100%	0%	20%	Good
Fair-Good	8	80%	20%	40%	Fair
Fair	6	60%	40%	60%	Poor
Poor-Fair	4	40%	60%	80%	Poor
Poor	2	20%	80%	100%	Unsatisfactory

Plan Type	Condition	Element No.	Asset	Qty.	UOM.	Unit Cost (\$)	Asset Value (\$)	Actual Asset Condition Score	Max Possible Score	Asset Weighting Based Upon Asset Value	Asset Condition Weighted Score	Max. Possible Weighted Score	Cond. (%)	Condition Rating
A10 Foundations														
Capital Replacement	Good	A10 Foundations	A10 Foundations	80,000.00	SF	11.60	928,000.00			100%	10.00	10.00		
		A10 Foundations					928,000.00	10			10.00	10.00	0%	Good
A20 Basement Constr					1									
Capital Replacement	Good	A20 Basement Construction	A20 Basement Construction	10,000.00	SF	8.90	89,000.00	10	10.00	100%	10.00	10.00		
		A20 Basement Construction	on				89,000.00	10			10.00	10.00	0%	Good
B10 SuperStructure														
Deferred Maintenance	Poor - Fair	B10 SuperStructure	Cracking CMU and Concrete Walls		LS	10,000.00	10,000.00		10.00	0%	0.02	0.04		
Capital Replacement	Good	B10 SuperStructure	B10 SuperStructure	180,700.00	SF	13.40				100%	9.96	9.96		
		B10 SuperStructure					2,431,380.00	14			9.98	10.00	0%	Good
B20 Exterior Enclosur														
Deferred Maintenance	Poor	B20 Exterior Enclosure	Recaulk expansion and control joints	500.00		13.16	6,580.00			0%	0.00	0.01		
Capital Replacement	Fair	B20 Exterior Enclosure	Paint Exterior Metal Grates at Windows	5,395.00		2.25	12,138.75			0%	0.01	0.01		
Capital Replacement	Good	B20 Exterior Enclosure	Precast Concrete Panels with Exposed	11,120.00		19.97	222,066.40			2%	0.18	0.18		
Capital Replacement	Fair - Good	B20 Exterior Enclosure	Repoint Brick Masonry Exterior Walls	3,200.00		25.96	83,072.00			1%	0.05	0.07		
Deferred Maintenance	Fair - Good	B20 Exterior Enclosure	Repair and Repoint Brick Masonry	250.00		25.96	6,490.00		10.00	0%	0.00	0.01		
Capital Replacement	Poor - Fair	B20 Exterior Enclosure	Exterior Windows	187,700.00		62.80			10.00	97%	3.87	9.68		
Capital Replacement	Fair - Good	B20 Exterior Enclosure	Exterior Metal Doors	42.00	EACH	1,500.00	63,000.00		10.00	1%	0.04	0.05		
		B20 Exterior Enclosure					12,180,907.15	46			4.16	10.00	58%	Poor
B30 Roofing														
Capital Replacement	Fair	B30 Roofing	Atrium Skylight	1,000.00		39.94	39,940.00			8%	0.47	0.78		
Deferred Maintenance	Poor - Fair	B30 Roofing	Modified Bitumen - Single Ply	80,000.00	SF	5.90	472,000.00		10.00	92%	3.69	9.22		
		B30 Roofing					511,940.00	10			4.16	10.00	58%	Poor
C10 Interior Construct														
Capital Replacement	Fair	C10 Interior Construction	Single Hollow Metal Door	65.00	EACH	1,200.00	78,000.00		10.00	100%	6.00	10.00		
		C10 Interior Construction					78,000.00	6			6.00	10.00	40%	Fair
C20 Stairs														
Capital Replacement	Good	C20 Stairs	C20 Stairs	7,450.00	SF	0.08	596.00			100%	10.00	10.00		
		C20 Stairs					596.00	10			10.00	10.00	0%	Good
C30 Interior Finishes														
Capital Replacement	Fair - Good	C30 Interior Finishes	Paint Interior Ceilings	46,925.00		11.60	544,330.00			15%	1.18	1.47		
Capital Replacement	Good	C30 Interior Finishes	Acoustic Ceiling System	87,575.00		9.68	847,726.00			23%	2.30	2.30		
Capital Replacement	Fair - Good	C30 Interior Finishes	Ceramic Tile Flooring	2,900.00		17.38	50,402.00			1%	0.11	0.14		
Capital Replacement	Fair	C30 Interior Finishes	Vinyl Tile Flooring	7,637.00		67.75	517,406.75		10.00	14%	0.84	1.40		
Deferred Maintenance	Poor	C30 Interior Finishes	Carpet Flooring	78.00		67.40	5,257.20			0%	0.00	0.01		
Capital Replacement	Good	C30 Interior Finishes	Wood Flooring - Premium	2,294.00		50.00	114,700.00			3%	0.31	0.31		
Capital Replacement	Good	C30 Interior Finishes	Quarry Tile Flooring	4,500.00		13.10	58,950.00			2%	0.16	0.16		
Capital Replacement	Fair - Good	C30 Interior Finishes	Paint Interior Walls	180,700.00		1.78	321,646.00			9%	0.70	0.87		
Capital Replacement	Good	C30 Interior Finishes	Vinyl Tile Flooring	9,529.00		67.75	645,589.75			17%	1.75	1.75		
Capital Replacement	Fair - Good	C30 Interior Finishes	Carpet Flooring	312.00		67.40	21,028.80			1%	0.05	0.06		
Capital Replacement	Fair	C30 Interior Finishes	Folding Wood Partition Walls	2,294.00		61.85	141,883.90			4%	0.23	0.38		
Deferred Maintenance	Poor - Fair	C30 Interior Finishes	Acoustic Ceiling System	33,200.00		9.68	321,376.00		10.00	9%	0.35	0.87		
Deferred Maintenance	Poor - Fair	C30 Interior Finishes	Vinyl Tile Flooring	1,486.00	SY	67.75	100,676.50		10.00	3%	0.11	0.27		
		C30 Interior Finishes					3,690,972.90	94			8.08	10.00	19%	Good
D20 Plumbing				ı										
Capital Replacement	Fair	D20 Plumbing	Floor Mounted Drinking Fountain	1.00	EACH	2,000.00	2,000.00	6	10.00	0%	0.01	0.02		

Powered by iPlan © 2013 4tell™ Solutions, LP.

All Rights Reserved. 4tell, iPlan (patent pending) Building Blocks, and Innovation for the Built Environment are trademarks of 4tell™ Solutions, LP Run Date: May 15, 2013



Uniformat Level 2 Asset Condition Rating For Hamilton Center

2012 iPlan Scoring												
Condition	Score		From	То	Rating							
Good	10	100%	0%	20%	Good							
Fair-Good	8	80%	20%	40%	Fair							
Fair	6	60%	40%	60%	Poor							
Poor-Fair	4	40%	60%	80%	Poor							
Poor	2	20%	80%	100%	Unsatisfactory							

Plan Type	Condition	Element No.	Asset	Qty.	UOM.	Unit Cost (\$)	Asset Value (\$)	Actual Asset Condition Score	Max Possible Score	Asset Weighting Based Upon Asset Value	Asset Condition Weighted Score	Max. Possible Weighted Score	Cond. (%)	Condition Rating
Capital Replacement	Good	D20 Plumbing	Domestic Hot Water Boiler	1.00	EACH	15,961.00	15,961.00	10	10.00	1%	0.15	0.15		
Capital Replacement	Fair	D20 Plumbing	Wall Hung Urinals		EACH	1,235.00	32,110.00			3%	0.18	0.29		
Capital Replacement	Fair	D20 Plumbing	Shower Components - Head, Arm,		EACH	532.00	20,216.00			2%	0.11	0.18		
Capital Replacement		D20 Plumbing	Domestic Water Piping System	180,700.00		3.15	569,205.00			52%	4.15	5.19		
Capital Replacement	Fair	D20 Plumbing	Sanitary Waste Piping	180,700.00		1.37	247,559.00			23%	1.35	2.26		
Capital Replacement	Good	D20 Plumbing	Floor Mounted Toilets		EACH	1,455.00	77,115.00			7%	0.70	0.70		
Deferred Maintenance	Poor	D20 Plumbing	Install Drinking Fountain Third Floor		EACH	2,545.00	2,545.00			0%	0.00	0.02		
Capital Replacement	Good	D20 Plumbing	Wall Hung Drinking Fountains		EACH	2,545.00	30,540.00			3%	0.28	0.28		
Capital Replacement	Fair - Good	D20 Plumbing	Wall Hung Lavatory Sinks		EACH	1,400.00	49,000.00			4%	0.36	0.45		
Capital Replacement	Good	D20 Plumbing	Domestic Hot Water Storage Tanks		EACH	25,000.00	50,000.00			5%	0.46	0.46		
Dapital Neplacement	Good	D20 Plumbing	Domestic Hot Water Storage Taliks	2.00	LACIT	25,000.00	1,096,251.00			J 70	7.75	10.00	22%	Fair
030 HVAC		D20 Fluilibilig				ļ	1,090,231.00	02			1.13	10.00	ZZ /0	Ган
Capital Replacement	Poor - Fair	D30 HVAC	Central Heating Boiler 2	1.00	EACH	199,525.53	199,525.53	4	10.00	12%	0.48	1.21		
Deferred Maintenance	Poor	D30 HVAC	Centrifugal Roof Exhaust Fan Systems		EACH	2,585.00	5,170.00			0%	0.01	0.03		
Capital Replacement	Good	D30 HVAC	Complete System- Outdoor and Indoor		TON	2,000.00	5,000.00			0%	0.03	0.03		
Capital Replacement	Fair	D30 HVAC	Central Air Handling Units		EACH	15,000.00	165,000.00		10.00	10%	0.60	1.00		
Capital Replacement	Poor - Fair	D30 HVAC	Unit Ventilators		EACH	7,685.00	530,265.00		10.00	32%	1.29	3.22		
Capital Replacement	Good	D30 HVAC	Recirculation Pumps, 25 HP		EACH	9,204.00	18,408.00			1%	0.11	0.11		
Capital Replacement	Good	D30 HVAC	Complete System- Outdoor and Indoor		TON	2,000.00	14,000.00			1%	0.08	0.08		
Deferred Maintenance	Poor	D30 HVAC	Boiler Room Piping & Valves	1.00		25,000.00	25,000.00		-	2%	0.03	0.15		
Capital Replacement	Poor - Fair	D30 HVAC	Central Heating Boiler 3		EACH	199,525.53	199,525.53		10.00	12%	0.48	1.21		
Capital Replacement	Good	D30 HVAC	Centrifugal Roof Exhaust Fan Systems		EACH	2,585.00	62,040.00		-	4%	0.38	0.38		
Deferred Maintenance	Poor	D30 HVAC	Commercial Kitchen Exhaust System		EACH	11,327.01	11,327.01			1%	0.01	0.07		
Deferred Maintenance	Poor	D30 HVAC	Metal Exhaust Hoods		EACH	2,500.00	42,500.00			3%	0.05	0.26		
Capital Replacement	Fair	D30 HVAC	Fin-Tube Convectors - Wall	372.00		130.00	48,360.00		10.00	3%	0.05	0.29		
Capital Replacement	Poor - Fair	D30 HVAC	Central Heating Boiler 1		EACH	199,525.53	199,525.53		10.00	12%	0.18	1.21		
•	Fair - Good	D30 HVAC	Window A/C Units	100.00		1,127.00	112,700.00		10.00	7%	0.55	0.68		
Capital Replacement												0.06		
Capital Replacement	Good	D30 HVAC	Complete System- Outdoor and Indoor	5.00	TON	2,000.00	10,000.00			1%	0.06	10.00	52%	Dear
040 Fire Protection Sy	rotomo	D30 HVAC					1,648,346.60	94			4.83	10.00	52%	Poor
Capital Replacement	Fair - Good	D40 Fire Protection System	ns Fire Extinguishers	30.00	EACH	250.00	7,500.00	8	10.00	100%	8.00	10.00		
		D40 Fire Protection Syste	ems				7,500.00	8			8.00	10.00	20%	Good
050 Electrical System	S													
Capital Replacement	Poor	D50 Electrical Systems	Central Fire Alarm Panel	1.00	EACH	12,000.00	12,000.00	2	10.00	2%	0.04	0.18		
Capital Replacement	Poor - Fair	D50 Electrical Systems	Panelboards - 120/208volts, 200amp		EACH	3,525.00	42,300.00		10.00	6%	0.25	0.63		
Capital Replacement	Fair	D50 Electrical Systems	Upgrade to T8 Fixtures	180,700.00		2.80	505,960.00			76%	4.55	7.58		
Deferred Maintenance	Poor	D50 Electrical Systems	Replace existing horn with horn/strobe		EACH	308.04	10,781.40			2%	0.03	0.16		
Capital Replacement	Poor - Fair	D50 Electrical Systems	Main Electrical Switchgear	2,000.00		31.95	63,900.00		10.00	10%	0.38	0.96		
Capital Replacement	Good	D50 Electrical Systems	Exit Lights L.E.D		EACH	345.32	13,812.80			2%	0.21	0.21		
Capital Replacement	Good	D50 Electrical Systems	Roof and Building Mounted Exterior		EACH	709.32	18,442.32			3%	0.28	0.28		
		D50 Electrical Systems				. 55.52	667,196.52			2,0	5.74	10.00	43%	Poor
E10 Equipment														
E10 Equipment Deferred Maintenance	Poor	E10 Equipment	Remove Abandoned Walk-in Coolers	2 00	LS	2 500 00	5 000 00	2	10.00	17%	0.33	1.67		
E10 Equipment Deferred Maintenance Capital Replacement	Poor Fair	E10 Equipment E10 Equipment	Remove Abandoned Walk-in Coolers Commercial Kitchen Food Service	2.00 1.00		2,500.00 25,000.00	5,000.00 25,000.00			17% 83%	0.33 5.00	1.67 8.33		



Uniformat Level 2 Asset Condition Rating For Hamilton Center

	2012 iPlan Scoring												
Condition	Score		From	То	Rating								
Good	10	100%	0%	20%	Good								
Fair-Good	8	80%	20%	40%	Fair								
Fair	6	60%	40%	60%	Poor								
Poor-Fair	4	40%	60%	80%	Poor								
Poor	2	20%	80%	100%	Unsatisfactory								

Plan Type	Condition	Element No.	Asset	Qty.	UOM.	Unit Cost (\$)	Asset Value (\$)	Actual Asset Condition Score	Max Possible Score	Asset Weighting Based Upon Asset Value	Asset Condition Weighted Score	Max. Possible Weighted Score	Cond. (%)	Condition Rating
Capital Replacement	Fair - Good	E20 Furnishings	E20 Furnishings	180,700.00	SF	0.13	23,491.00	8	10.00	100%	8.00	10.00		
•		E20 Furnishings					23,491.00	8			8.00	10.00	20%	Good
G20 Site Improvement	:s													
Capital Replacement	Good	G20 Site Improvements	Concrete Retaining Walls	2,500.00	SF	42.72	106,800.00	10	10.00	16%	1.57	1.57		
Capital Replacement	Good	G20 Site Improvements	Children's Playground Equipment	2.00	EACH	12,000.00	24,000.00	10	10.00	4%	0.35	0.35		
Deferred Maintenance	Poor	G20 Site Improvements	Install Metal Handrails at Site Steps	24.00	LF	47.39	1,137.36	2	10.00	0%	0.00	0.02		
Deferred Maintenance	Poor	G20 Site Improvements	Cracking and Spalling Concrete	1,880.00	LF	33.13	62,284.40	2	10.00	9%	0.18	0.91		
Capital Replacement	Fair	G20 Site Improvements	Concrete Steps	320.00	SF	87.00	27,840.00	6	10.00	4%	0.24	0.41		
Deferred Maintenance	Poor - Fair	G20 Site Improvements	Restripe Parking Lot	39.00	EACH	35.00	1,365.00	4	10.00	0%	0.01	0.02		
Deferred Maintenance	Poor - Fair	G20 Site Improvements	Concrete Pavement – Parking Lot and	8,180.00	SF	8.09	66,176.20	4	10.00	10%	0.39	0.97		
Deferred Maintenance	Poor - Fair	G20 Site Improvements	Chain Link Galvanized Fence	530.00	LF	5.00	2,650.00	4	10.00	0%	0.02	0.04		
Deferred Maintenance	Poor - Fair	G20 Site Improvements	Re-grading landscape and	555.00	SY	26.39	14,646.45	4	10.00	2%	0.09	0.21		
Capital Replacement	Fair	G20 Site Improvements	Concrete Paved Parking Lot	13,650.00	SF	8.09	110,428.50	6	10.00	16%	0.97	1.62		
Capital Replacement	Fair	G20 Site Improvements	Concrete Paved Drive Lane	32,720.00	SF	8.09	264,704.80	6	10.00	39%	2.33	3.88		
' '		G20 Site Improvements					682,032.71	58			6.15	10.00	39%	Fair
G30 Site Civil/Mechan	ical Utilities	•					,							
Capital Replacement	Fair - Good	G30 Site Civil/Mechanical Utilities	G30 Site Civil/Mechanical Utilities	230,000.00	SF	0.56	128,800.00	8	10.00	100%	8.00	10.00		
		G30 Site Civil/Mechanical U	Utilities				128,800.00	8			8.00	10.00	20%	Good
G40 Site Electrical Uti	lities													
Capital Replacement	Fair	G40 Site Electrical Utilities	G40 Site Electrical Utilities	230,000.00	SF	0.89	204,700.00	6	10.00	91%	5.45	9.08		
Capital Replacement	Fair	G40 Site Electrical Utilities	Emergency Generator, 30 kW	1.00	EACH	20,670.00	20,670.00	6	10.00	9%	0.55	0.92		
		G40 Site Electrical Utilities					225,370.00	12			6.00	10.00	40%	Fair
Z10 General Requirem	ents						•							
Plant Adaptation	Good	Z10 General Requirements	Z1010.3 Consider: Fire Protection	1.00	LS	1,366,387.00	1,366,387.00	10	10.00	43%	4.29	4.29		
Plant Adaptation	Good	Z10 General Requirements	Z1010.2 Consider: ADA Investments	1.00	LS	88,000.00	88,000.00	10	10.00	3%	0.28	0.28		
Plant Adaptation	Good	Z10 General Requirements	Z1010.6 Consider: LEED Investments	1.00	LS	253,523.00	253,523.00	10	10.00	8%	0.80	0.80		
Plant Adaptation	Fair	Z10 General Requirements	Green Roof	80,000.00	SF	12.23	978,240.00	6	10.00	31%	1.84	3.07		
Plant Adaptation	Fair	Z10 General Requirements	Green Roof Structural Evaluation by	1.00		7,500.00	7,500.00	6	10.00	0%	0.01	0.02		
Plant Adaptation	Good	Z10 General Requirements	Z1010.7 Consider: Safety Security	1.00		394,559.00	394,559.00	10		12%	1.24	1.24		
Plant Adaptation	Good	Z10 General Requirements	Z1010.5 Consider: Haz Mat Investments	1.00		500.00	500.00			0%	0.00	0.00		
Plant Adaptation	Good		Z1010.1 Consider: Access Contro	1.00		97,440.00	97,440.00	10		3%	0.31	0.31		
· ·		Z10 General Requirements				,	3,186,149.00	72			8.76	10.00	12%	Good



Assessment Images for Hamilton Center Property Images

Primary Image:

Front elevation of building

Image 2:

Building identification on front canopy

Image 3:

Left side elevation of building







Assessment Images for Hamilton Center

Image 4:

Right side elevation of building



Image 5:

Rear elevation of building



Image 6:

Overview of rear parking lot



Asset Images

B10 - SUPERSTRUCTURE

B10 SuperStructure

Concrete superstructure:

Asset Photo: B10 SuperStructure.1



B1032 - CONCRETE FRAME STRUCTURE

Cracking CMU and Concrete Walls

Shifting CMU block wall classroom 324:

Asset Photo: Cracking CMU and Concrete Walls.1



Cracking concrete beam classroom 322:

Asset Photo: Cracking CMU and Concrete Walls.2

B2011 - EXTERIOR WALL CONSTRUCTION

Recaulk expansion and control joints



Asset Images

Cracking expansion joint front exterior wall:

Asset Photo: Recaulk expansion and control joints.1



Precast Concrete Panels with Exposed Aggregate

Precast Concrete Panels with Exposed Aggregate:

Asset Photo: Precast Concrete Panels with Exposed Aggregate.1



Repoint Brick Masonry Exterior Walls

Brick masonry exterior wall:

Asset Photo: Repoint Brick Masonry Exterior Walls.1



Repair and Repoint Brick Masonry Exterior Walls



Asset Images

Missing mortar at brick masonry east side of building:

Asset Photo: Repair and Repoint Brick Masonry Exterior Walls.1



Cracking brick masonry east side of building:

Asset Photo: Repair and Repoint Brick Masonry Exterior Walls.2

B2021 - WINDOWS

Paint Exterior Metal Grates at Windows

Metal grates covering at windows:

Asset Photo: Paint Exterior Metal Grates at Windows.1



Exterior Windows



Asset Images

Exterior windows:

Asset Photo: Exterior Windows.1



B2039 - OTHER DOORS & ENTRANCES

Exterior Metal Doors

Exterior metal doors:

Asset Photo: Exterior Metal Doors.1



B3011 - ROOF FINISHES

Modified Bitumen - Single Ply

Flat roof:

Asset Photo: Modified Bitumen - Single Ply.1






Asset Images

Condition of roof:

Asset Photo: Modified Bitumen - Single Ply.2



Opening at roof seam:

Asset Photo: Modified Bitumen - Single Ply.3

B3021 - GLAZED ROOF OPENINGS

Atrium Skylight

Skylight over central Atrium:

Asset Photo: Atrium Skylight.1



C1021 - INTERIOR DOORS

Single Hollow Metal Door



Asset Images

Interior door:

Asset Photo: Single Hollow Metal Door.1



C20 - STAIRS

C20 Stairs

Concrete stair systems:

Asset Photo: C20 Stairs.1



C3012 - WALL FINISHES TO INTERIOR WALLS

Paint Interior Walls

Painted wall finishes in corridor:

Asset Photo: Paint Interior Walls.1




Folding Wood Partition Walls



Asset Images

Gym folding wood partition wall:

Asset Photo: Folding Wood Partition Walls.1



C3024 - FLOORING

Ceramic Tile Flooring

Restroom ceramic tile flooring:

Asset Photo: Ceramic Tile Flooring.1



Vinyl Tile Flooring

Storage room vinyl tile flooring:

Asset Photo: Vinyl Tile Flooring.1



Wood Flooring - Premium



Asset Images

Gym wood flooring:

Asset Photo: Wood Flooring - Premium.1



Quarry Tile Flooring

Kitchen quarry tile flooring:

Asset Photo: Quarry Tile Flooring.1



Vinyl Tile Flooring

Corridor vinyl tile flooring:

Asset Photo: Vinyl Tile Flooring.1





Asset Images

Classroom vinyl tile flooring:

Asset Photo: Vinyl Tile Flooring.2



Vinyl Tile Flooring

Damaged 9X9 vinyl tile stage dressing room:

Asset Photo: Vinyl Tile Flooring.1



Third floor storage room 9X9 vinyl tile:

Asset Photo: Vinyl Tile Flooring.2

C3025 - CARPETING

Carpet Flooring



Asset Images

Carpeting at third floor room 300:

Asset Photo: Broadloom Deluxe with Padding.1



Carpet Flooring

Office carpet flooring:

Asset Photo: Carpet Flooring.1



C3031 - CEILING FINISHES

Paint Interior Ceilings

Painted ceiling finishes at auditorium:

Asset Photo: Paint Interior Ceilings.1



C3032 - SUSPENDED CEILINGS

Acoustic Ceiling System



Asset Images

Suspended ceiling tiles:

Asset Photo: Acoustic Ceiling System.1



Acoustic Ceiling System

Missing ceiling tiles third floor:

Asset Photo: Acoustic Ceiling System.1



D2011 - WATER CLOSETS

Floor Mounted Toilets

Restroom toilet:

Asset Photo: Floor Mounted Toilets.1



D2012 - URINALS

Wall Hung Urinals



Asset Images

Wall hung urinals:

Asset Photo: Wall Hung Urinals.1



D2013 - LAVATORIES

Wall Hung Lavatory Sinks

Restroom lavatory sinks:

Asset Photo: Wall Hung Lavatory Sinks.1



D2017 - SHOWERS

Shower Components - Head, Arm, Bypass, Stops, Handles

Locker-room showers:

Asset Photo: Shower Components - Head, Arm, Bypass, Stops, Handles.1



D2018 - DRINKING FOUNTAINS AND COOLERS

Floor Mounted Drinking Fountain



Asset Images

Floor mounted drinking fountain:

Asset Photo: Floor Mounted Drinking Fountain.1



Install Drinking Fountain Third Floor Corridor

Missing drinking fountain third floor corridor:

Asset Photo: Install Drinking Fountain Third Floor Corridor.1



Wall Hung Drinking Fountains

Wall Hung drinking fountain in corridor:

Asset Photo: Wall Hung Drinking Fountains.1



D2021 - COLD WATER SERVICE


Domestic Water Piping System



Asset Images

Copper domestic water piping:

Asset Photo: Domestic Water Piping System.1



D2022 - HOT WATER SERVICE

Domestic Hot Water Boiler

Domestic water boiler:

Asset Photo: Domestic Hot Water Boiler.1



D2023 - DOMESTIC WATER SUPPLY EQUIPMENT

Domestic Hot Water Storage Tanks

Domestic water storage tanks:

Asset Photo: Domestic Hot Water Storage Tanks.1



D2031 - WASTE PIPING


Sanitary Waste Piping



Asset Images

Sanitary waste piping:

Asset Photo: Sanitary Waste Piping.1



D3021 - BOILERS

Central Heating Boiler 2

Heating boiler 2:

Asset Photo: Central Heating Boiler 2.1



Central Heating Boiler 3

Heating boiler 3:

Asset Photo: Central Heating Boiler 3.1



Central Heating Boiler 1



Asset Images

Heating boiler 1:

Asset Photo: Central Heating Boiler 1.1



D3022 - BOILER ROOM PIPING & SPECIALTIES

Recirculation Pumps, 25 HP

Recirculation pumps for heating system:

Asset Photo: Recirculation Pumps, 25 HP.1



Boiler Room Piping & Valves

Water on boiler room floor:

Asset Photo: Boiler Room Piping & Valves.1






Asset Images

Leaking pipe/valve in boiler room:

Asset Photo: Boiler Room Piping & Valves.2



D3023 - AUXILIARY EQUIPMENT

Fin-Tube Convectors - Wall

Hydronic Convector:

Asset Photo: Fin-Tube Convectors - Wall.1



D3041 - AIR DISTRIBUTION SYSTEMS

Central Air Handling Units

Air handling unit on steel mezzanine:

Asset Photo: Central Air Handling Units.1





Asset Images

Air handling unit in mechanical-storage room 6:

Asset Photo: Central Air Handling Units.2



Unit Ventilators

Unit ventilator:

Asset Photo: Unit Ventilators.1



D3042 - EXHAUST VENTILATION SYSTEMS

Centrifugal Roof Exhaust Fan Systems

Roof exhaust fan missing cover:

Asset Photo: Centrifugal Roof Exhaust Fan Systems.1



Centrifugal Roof Exhaust Fan Systems



Asset Images

Roof mounted exhaust fan:

Asset Photo: Centrifugal Roof Exhaust Fan Systems.1



Commercial Kitchen Exhaust System

Non operating kitchen exhaust hood:

Asset Photo: Commercial Kitchen Exhaust System.1



Metal Exhaust Hoods

Rusting roof exhaust hood:

Asset Photo: Metal Exhaust Hoods.1



D3051 - TERMINAL SELF-CONTAINED UNITS

Window A/C Units



Asset Images

Window A/C units:

Asset Photo: Window A/C Units.1



D3053 - SPLIT-SYSTEMS

Complete System- Outdoor and Indoor unit

Rooftop condenser:

Asset Photo: Complete System- Outdoor and Indoor unit.1



Complete System- Outdoor and Indoor unit

Rooftop condensers:

Asset Photo: Complete System- Outdoor and Indoor unit.1



Complete System- Outdoor and Indoor unit



Asset Images

Rooftop condensers:

Asset Photo: Complete System- Outdoor and Indoor unit.1



D4031 - FIRE EXTINGUISHERS

Fire Extinguishers

Fire extinguisher:

Asset Photo: Fire Extinguishers.1



D5012 - LOW TENSION SERVICE & DIST.

Panelboards - 120/208volts, 200amp

Original FPE electrical panels:

Asset Photo: Panelboards - 120/208volts, 200amp.1



Main Electrical Switchgear



Asset Images

Original FPE electrical switchgear:

Asset Photo: Main Electrical Switchgear.1



D5022 - LIGHTING EQUIPMENT

Upgrade to T8 Fixtures

Older T-12 light fixtures:

Asset Photo: Upgrade to T8 Fixtures.1



Roof and Building Mounted Exterior Light Fixtures

Roof mounted exterior lights:

Asset Photo: Roof and Building Mounted Exterior Light Fixtures.1



D5037 - FIRE ALARM SYSTEMS

Central Fire Alarm Panel



Asset Images

Fire alarm panel:

Asset Photo: Central Fire Alarm Panel.1



Replace existing horn with horn/strobe

Missing strobe alarms in building:

Asset Photo: Replace existing horn with horn/strobe .1



D5092 - EMERGENCY LIGHT & POWER SYSTEMS

Exit Lights L.E.D

Illuminated exit sign:

Asset Photo: Exit Lights L.E.D.1



E1093 - FOOD SERVICE EQUIPMENT

Remove Abandoned Walk-in Coolers



Asset Images

Abandoned walk-in cooler at kitchen:

Asset Photo: Remove Abandoned Walk-in Coolers.1



Commercial Kitchen Food Service Equipment

Commercial kitchen:

Asset Photo: Commercial Kitchen Food Service Equipment.1



E20 - FURNISHINGS

E20 Furnishings

Third floor classroom:

Asset Photo: E20 Furnishings.1



G2021 - BASES AND SUB-BASES

Concrete Pavement – Parking Lot and Drive Lane



Asset Images

Deteriorated and cracked concrete pavement:

Asset Photo: Concrete Paved Parking Lot and Drive Lane.1



Concrete Paved Parking Lot

Concrete paved parking lot:

Asset Photo: Concrete Paved Parking Lot and Drive Lane.1



Concrete Paved Drive Lane

Concrete paved drive lane:

Asset Photo: Concrete Paved Parking Lot and Drive Lane.1



G2025 - MARKINGS & SIGNAGE

Restripe Parking Lot



Asset Images

Worn pavement markings at rear parking lot:

Asset Photo: Restripe Parking Lot.1



G2031 - PAVING & SURFACING

Cracking and Spalling Concrete Sidewalks

Spalling concrete sidewalks front of school:

Asset Photo: Cracking and Spalling Concrete Sidewalks.1



Condition of concrete sidewalks west side of school:

Asset Photo: Cracking and Spalling Concrete Sidewalks.2

G2033 - EXTERIOR STEPS


Install Metal Handrails at Site Steps



Asset Images

Missing handrail at steps west side of building:

Asset Photo: Install Metal Handrails at Site Steps.1



Concrete Steps

Concrete steps:

Asset Photo: Concrete Steps.1



G2041 - FENCES & GATES

Chain Link Galvanized Fence

Condition of site chain link fencing:

Asset Photo: Chain Link Galvanized Fence.1



G2042 - RETAINING WALLS

Concrete Retaining Walls



Asset Images

Concrete retaining wall:

Asset Photo: Concrete Retaining Walls.1



G2049 - MISCELLANEOUS STRUCTURES

Children's Playground Equipment

Children play equipment (1 of 2):

Asset Photo: Children's Playground Equipment.1



G2053 - TOP SOIL AND PLANTING BEDS

Re-grading landscape and establishment of ground cover

Landscape ponding area west side of school:

Asset Photo: Re-grading landscape and establishment of ground cover .1





Asset Images

Bare soils at landscaping south side of school:

Asset Photo: Re-grading landscape and establishment of ground cover .2



G4092 - SITE EMERGENCY POWER GENERATION

Emergency Generator, 30 kW

Emergency generator:

Asset Photo: Emergency Generator, 30 kW.1



Z1010.4 - CONSIDER: GREEN ROOF INVESTMENTS


Green Roof


Flat roof:

Asset Photo: Green Roof.1















PROJECT DCPS Space Analysis

PREPARED BY CI - 4tell / EMG

CLIENTDistrict of Columbia
Department of
General Services

4TELL SOLUTIONS
15 Franklin Street
Portland, ME 04101
800.750.4424

4tell










CLIENTDistrict of Columbia
Department of
General Services

PROJECT DCPS Space Analysis

issue 05.01.2013

prepared by CI - 4tell / EMG







2nd Floor Hamilton Elementary

PREPARED BY CI - 4tell / EMG

PROJECT DCPS Space Analysis


issue 05.01.2013

CLIENT
District of Columbia
Department of
General Services

4TELL SOLUTIONS
15 Franklin Street
Portland, ME 04101
800.750.4424

4tell

4tell



PROJECT DCPS Space Analysis

CLIENT
District of Columbia
Department of
General Services

PREPARED BY CI - 4tell / EMG **issue** 05.01.2013

3rd Floor Hamilton Elementary



Room Inventory		Hamilton Center School			1401 Brentwood Parkway NE Washington DC			
Space No. [NOTE 1]	Room No. [From Pathways]	Space Type [NOTE 1]	Space Use [NOTE 1]	Space Use Detail	Room Type [From Pathways]	Approx. Square Footage [EMG Field Team]	Approx. Dimension in Feet [EMG Field Team]	
44		Building Services	Storage			432	18	24
45		Building Services	Storage			495	15	33
46		Building Services	Storage			289	17	17
47	1001	Administration	Conference Room			1034	22	47
48		Building Services	Vestibule			308	22	14
49		Building Services	Vestibule			308	22	14
50	1005	Instruction	Classroom			704	32	22
51	1008	Administration	Office			704	32	22
52	123	Instruction	Classroom			704	32	22
53	121	Instruction	Classroom			704	32	22
54		Instruction	Classroom			1034	47	22
55		Building Services	Corridor			1962	9	218
56		Building Services	Corridor			1962	9	218
57		Building Services	Corridor			920	8	115
58		Instruction	Classroom			1200	25	48
59		Instruction	Classroom			1200	25	48
60		Instruction	Classroom			800	25	32
61		Instruction	Classroom			800	25	32
62		Instruction	Classroom			800	25	32
63		Administration	Conference Room			325	25	13
64		Instruction	Classroom			800	25	32
65		Instruction	Classroom			925	25	37
66		Instruction	Classroom			800	25	32
67		Instruction	Classroom			800	25	32
68		Instruction	Classroom			950	25	38
74		Instruction	Classroom			1350	25	54
75	237	Instruction	Classroom			1034	47	22
76		Administration	Office			384	24	16
77		Administration	Office			252	18	14
78		Administration	Office			252	18	14
79		Administration	Office			336	24	14
80	233	Instruction Support	Computer Lab			1034	47	22
81	231	Instruction	Classroom			704	22	32
82		Building Services	Vestibule			378	27	14
83		Building Services	Vestibule			840	28	30
86	229	Instruction	Classroom			704	32	22
87	227	Auxiliary	Library			1034	47	22
88		Administration	Office			294	21	14
89		Building Services	Storage			81	9	9
90		Building Services	Storage			81	9	9
91		Administration	Office			528	24	22
92		Administration	Office			528	24	22

Locker Room

Locker Room Area

Locker Room Area

Girls

140

141

142

Building Services

Building Services

Building Services

1395

308

418

45 31

22 14

22 19

Room Inventory		Han	1401 Brentwood Parkway NE Washington DC					
Space No. [NOTE 1]	Room No. [From Pathways]	Space Type [NOTE 1]	Space Use [NOTE 1]	Space Use Detail	Room Type [From Pathways]	Approx. Square Footage [EMG Field Team]	Approx. Dimension in Feet [EMG Field Team]	
143		Auxiliary	Gymnasium			7480	68	110
144		Auxiliary	Storage			420	15	28
145		Building Services	Storage			196	14	14
146		Building Services	Storage			390	13	30
147		Building Services	Storage			208	13	16
148		Building Services	Storage			286	13	22
149		Building Services	Storage			88	11	8
150		Building Services	Storage			224	14	16
151		Building Services	Locker Room	Boys		1395	45	31
152		Building Services	Locker Room Area	-		682	22	31
153		Building Services	Locker Room Area			418	22	19
155		Building Services	Storage			128	16	8
156	215	Instruction	Classroom			770	35	22
157	217	Instruction	Classroom			770	35	22
158		Building Services	Corridor			5000	10	500
159		Building Services	Corridor			5000	10	500
160		Building Services	Corridor			912	8	114
161		Building Services	Corridor			912	8	114
162		Instruction	Classroom			1034	47	22
163		Instruction	Classroom			1408	64	22
165		Instruction	Classroom			704	32	22
166		Instruction	Classroom			704	32	22
167		Instruction	Classroom			1056	48	22
168		Building Services	Storage			252	18	14
169		Instruction	Classroom			704	32	22
170		Instruction	Classroom			704	32	22
171	312	Instruction	Classroom			704	32	22
172		Instruction	Classroom			704	32	22
173	310	Building Services	Storage			345	15	23
174	308	Instruction	Classroom			1200	25	48
175	322	Instruction	Classroom			1034	47	22
176	323	Instruction	Classroom			616	28	22
177	324	Instruction	Classroom			704	32	22
178		Instruction	Classroom			704	32	22
179	325	Instruction	Classroom			704	32	22
180	326	Instruction	Classroom			704	32	22
181		Instruction	Classroom			704	32	22
182	328	Instruction	Classroom			704	32	22
183		Instruction	Classroom			704	32	22
184		Instruction	Classroom			704	32	22
185		Instruction	Classroom			1034	47	22
186		Instruction	Classroom			770	35	22



4TELL SOLUTIONS15 Franklin Street
Portland, ME 04101
800.750.4424

CLIENT
District of Columbia
Department of
General Services

PROJECT DCPS Space Analysis

issue 05.01.2013

Room Inventory Elementary Hamilton

[Note 1] Source - Government of DC - Office of Public Facility Modernization - Recommendation to Revised Official Building Capacity





4TELL SOLUTIONS
15 Franklin Street
Portland, ME 04101
800.750.4424

CLIENT
District of Columbia
Department of
General Services


PROJECT DCPS Space Analysis

PREPARED BY CI - 4tell / EMG **issue** 05.01.2013


Room Inventory Elementary Hamilton

4TELL SOLUTIONS
15 Franklin Street
Portland, ME 04101
800.750.4424

CLIENT
District of Columbia
Department of
General Services



1st Floor



Fixture Diagrams Hamilton Elementary


issue 05.01.2013

issue 05.01.2013

Fixture Diagrams Hamilton Elementary



2nd Floor





CLIENT
District of Columbia
Department of
General Services

issue 05.01.2013

Fixture Diagrams Hamilton Elementary



3rd Floor

