301 Douglass Street NE, Washington, DC



INITIAL YEAR BUILT	1971
BUILDING AREA	67,200 SF
CURRENT PROGRAM CAPACITY	350
ENROLLMENT 2009-2010	149
WARD	5
PROPOSED PROGRAM CAPACITY	450



Site Plan

301 Douglass Street NE, Washington, DC

## **PROPOSED PRGRAM PROFILE**

GRADE CONFIGURATION	PS-8
SQ. FT. (EXISTING)	67,200
SQ. FT. (ADDITION)	

ТҮРЕ	PROPOSED
Pre-School	1
Pre-Kindergarten	2
Kindergarten	2
1	2
2	2
3	2
4	2
5	2
6	2
7	2
8	2
Gym	1
Bleachers	
Locker Rooms	2
Gym-Cafeteria	
Cafetorium	

ТҮРЕ	PROPOSED
Gym-Cafetorium	
Gym-Auditorium	
Auditorium	
Multi-Purpose	1
Cafeteria	
Kitchen Services	1
Special Education	2
Administrative	1
Media Center	1
Computer Lab	1
OT/PT	1
Science Lab	1
Art	
Music	1
Teacher Workroom	3
Parent Resource	2

### **Proposed Planning Profiles**

The inventory of spaces listed here is intended to outline the program of educational and support spaces necessary to support the proposed program capacity. Individual educational specifications and facility programs will be developed with the School Improvement and School Planning / Design teams at the time of project initiation.

301 Douglass Street NE, Washington, DC

CONDITION ASSES	SMENT			
	MARCE S	_	Building System	2008 Rating
77.1			A Compliance	Poor
TA AT		Con	veying Systems	Fair
A ANC		Elec	trical	Poor
- Ac-		Exte	erior Finish	Fair
ALK . Part Comme		HVAC		Poor
		Interior Finish		Fair
		Plur	nbing	Poor
		Roo	f	Poor
A CONTRACTOR OF A DATE	THE REAL PROPERTY OF	Stru	cture	Good
	AL 178 794 2		hnology	Unsatisfactory
Condition Assessment The body of information summarized below is ba in 2006 and updated by visual observations cond OPEFM in 2007 and 2008 are noted in red text in under various OPEFM programs is provided at th	lucted in 2007. Improvement initiatives completed a each section. An overall summary of work com	d by	adherence with the Facility Condition Ind	and level of replacement need for an entire system, in lex (FCI) System, categorizing systems as 50), "Poor" (FCI 0.51 – 0.85), or "Unsatisfactory" (FCI > .86).
Comments:				
1 Conveying System	There is an elevator present, but it is obsolete and does not meet code requirements. An upgraded model should be installed.			
2 Electrical	The electrical system should be replaced due to the fact the current service is outdated. Fire alarm, public address, and telephone system is obsolete. Wiring is original and should be replaced. 2007: Replace light ballasts.			
3 Exterior Finish	Generally in fair condition. No major deficiencies were noted, although re-pointing of brickwork is recommended for maintenance. 2007: Replaced exterior lighting.			
4 Structure	Minor cracking observed during assessment. Structural analysis recommended for cracks before significant exterior finish damage occurs.			
5 HVAC	The current system was upgraded from a heating-only system to a dual temperature system. As the pipes were originally designed for heating only, it has shocked the system and many ceilings have been damaged because of the resulting leaks. The HVAC system needs to be replaced. The chiller can be salvaged as it was installed in the last five to ten years and has remaining life. 2007: central A/C repairs. 2008: Repairs to Boilers and Classroom heating units. Installed 6 window A/C units. 2009: New AC HVAC Cooling Tower			
6 Interior Finish	Most finishes are in fair condition. Aside from replacing ceiling tiles, most flooring and walls are in need of only minor repair work. Interior windows are in poor condition. Patching and painting of plaster finishes is required. 2007: Ceiling repairs, door hardware repairs, classroom painting.			
7 Plumbing	No fire suppression system is present. Bathroom fixtures are obsolete and do not meet modern code requirements. Shower drains are also deficient and need repair. Visible piping appears to be acceptable, but additional inspection of hidden pipe sections may indicate additional problems due to the known water leakage. 2007: Water cooler installation/repairs.			
8 Roof	The roof structure is in fair condition. Replacement of flashing and clearing debris from gutters will reduce water infiltration into the building.			

301 Douglass Street NE, Washington, DC

9 ADA Compliance	Conveying needs improvement. Bathroom fixtures also need to be upgraded.
10 Technology	The equipment appears to be in fair to poor condition. PCs present are old and in visibly poor condition. Upgrades to software and hardware, and dedicated spaces to technological equipment are recommended
11 Grounds	The grounds are in fair to poor condition. Curb cuts should be added and general maintenance performed to seal concrete to prevent further cracking and spalling. 2009: Received Playground Renovations

301 Douglass Street NE, Washington, DC

## **RECENT HISTORY OF MODERNIZATION**

### 2007 TARGETED REPAIRS

- Interior Finishes Door Replacements/Door Hardware Repair
- Interior Finishes Drywall & Ceiling Repairs
- Interior Finishes Select Carpet Replacements/Flooring Repairs
- Interior Finishes Painting/Plastering
- Plumbing Repairs Restrooms/Fixtures & Flush Valves; Water Fountains
- Electrical Repairs Lighting & Power
- Mechanical Repairs AHU & Boiler Repairs, HVAC Filter Replacement
- Exterior Work & Building Envelope Lighting, Site Work, Playground, etc.
- Other Work Orders

### 2008 STABILIZATIONS


C AC Window Units Installations & Electrical Upgrades

### 2009 STABILIZATION & SPECIAL PROJECTS


- Received Playground Renovations
- New AC HVAC Cooling Tower

### LEGACY PROJECTS - OTHER STABLIZATIONS

- Mechanical Boiler Replacements/Heating Plant Upgrades
- Mechanical Terminal Units Replacements




Ground Floor




- Special Education
- Elevator Addition


#### **Concept Plans**

These floor plans represent planning concepts for proposed facility use, aligning the proposed program capacity, the proposed planning profiles, and the conceptual reconfiguration of the building. Each project is subject to a formal design process, incorporating input from the School Improvement team at the time of project initiation.




First Floor






Second Floor



#### **Concept Plans**

These floor plans represent planning concepts for proposed facility use, aligning the proposed program capacity, the proposed planning profiles, and the conceptual reconfiguration of the building. Each project is subject to a formal design process, incorporating input from the School Improvement team at the time of project initiation.



Third Floor

