



DC PCSB surveyed public charter schools to collect information on facility conditions for all public charter schools through its SY15-16 Public Charter Facility survey. The results are presented in summary form below.

**Public charter school facility needs and conditions, SY15-16**

Source: DC PCSB SY15-16 Public Charter Facility Survey

Facility needs	
Percent of facilities that support the school's academic mission	77%
Percent of facilities that are easily accessible by public transportation	80%
Percent of facilities without safety concerns	89%
Percent of facilities with indoor quality that is comfortable for students	69%
Facility conditions	
Percent of facilities with no state of repair concerns	42%
Percent of facilities with state of repair concerns for the following building elements:	
HVAC	32%
Roof	17%
Conveying Systems (elevators and ramps)	14%
Interior Finish	14%
Plumbing	12%
Fire Protection Systems	11%
Exterior Enclosure	7%
Interior Construction	6%
Stairs	5%
Foundations	5%
Basement construction	4%
Electrical Systems	4%
Carbon Monoxide Detector	1%
Specialized spaces	
Percent of facilities with no concerns related to the adequacy of specialized spaces	15%
Percent of facilities with concerns related to the adequacy of the following specialized spaces:	
Places to connect with the community	7%
Teacher professional space	22%
Nurse's suite	28%
Specialized learning areas (i.e. arts & sciences)	36%
Outdoor learning areas	42%
Health & physical fitness areas	44%